

CUSTOMER **PM0010-Vehicle Servicing Records**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #24365		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	26/07/2019 - 10:22 AM	JOB COMPLETED	26/07/2019 - 10:58 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h17

DESCRIPTION

Mitsubishi Triton Ute 1DIU447

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE	05/06/2019
VEHICLE REGISTRATION?	Mitsubishi Triton2 1DIU447 Vin No MMAERKA40AD012177 Eng No 4D56UCBX5738 Year 2010
DESCRIPTION OF WORK DONE	Investigate excess smoking from exhaust + 4 Cyl service
PI NUMBER	4601
VALUE OF WORK DONE	366.00



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED?	Yes
WHAT SPARES WERE PURCHASED?	Air flow meter
HOW MUCH DID THE SPARES COST?	440.00


SERVICE INFO

CURRENT ODOMETER READING KMS	222,677
NEXT SERVICE DUE AT?	233,000
WAS THE OIL & FILTER CHANGED?	Yes
WAS THE AIR FILTER CHANGED?	No
WERE THE BRAKE PADS CHANGED?	No


COMMENTS SECTION

CPAR ISSUED? -
CPAR REFERENCE NUMBER? -
ANY ADDITIONAL COMMENTS -
SIGNATURE

SIGNATURES

A handwritten signature consisting of several overlapping, fluid loops and a vertical stroke.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, fluid loops and a vertical stroke, similar to the one on the left.

E'Co Australia Pty Ltd (Eco
Inspections)