



CUSTOMER

PM0010-Vehicle Servicing Records
Revision: Version 4 Effective Date: 13 July 2018
Issued By: Steve Claridge Approved By: Mark Keay


Table with 4 columns: JOB #8599, JOB TYPE, SCHEDULED, SCHEDULED DURATION, JOB REPORT, TECHNICIAN, JOB COMPLETED, COMPLETED DURATION, Eco Inspections, Eco Inspections, 25/09/2018 - 04:23 PM, 00h02

DESCRIPTION

Truck 4 1CEM 814

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE: 21/08/2018
VEHICLE REGISTRATION?: Truck 4 Canter 1CEM814
DESCRIPTION OF WORK DONE: Replace Torsion Spring
PI NUMBER: 3813
VALUE OF WORK DONE: -



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? Yes
WHAT SPARES WERE PURCHASED? Torsion Spring
HOW MUCH DID THE SPARES COST? 75.57

SERVICE INFO

CURRENT ODOMETER READING KMS: -
NEXT SERVICE DUE AT?: -
WAS THE OIL & FILTER CHANGED?: -
WAS THE AIR FILTER CHANGED?: -
WERE THE BRAKE PADS CHANGED?: -


COMMENTS SECTION

CPAR ISSUED? -
CPAR REFERENCE NUMBER? -
ANY ADDITIONAL COMMENTS -
SIGNATURE

SIGNATURES

A handwritten signature consisting of several overlapping, fluid loops and a vertical stroke at the bottom.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, fluid loops and a vertical stroke at the bottom, similar to the one on the left.

ECo Australia Pty Ltd (Eco
Inspections)