

CUSTOMER **PM0010-Vehicle Servicing Records**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #9588		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	23/10/2018 - 12:37 PM	JOB COMPLETED	23/10/2018 - 12:45 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h06

DESCRIPTION

Truck 4 1CEM 814

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE 04/10/2018
 VEHICLE REGISTRATION? Truck 4 Canter 1CEM814
 DESCRIPTION OF WORK DONE Truck Service
 PI NUMBER 3989
 VALUE OF WORK DONE 425.00



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? No

SERVICE INFO

CURRENT ODOMETER READING KMS 335,852
 NEXT SERVICE DUE AT? 346,000
 WAS THE OIL & FILTER CHANGED? Yes
 WAS THE AIR FILTER CHANGED? Yes
 WERE THE BRAKE PADS CHANGED? No

COMMENTS SECTION


CPAR ISSUED? -
 CPAR REFERENCE NUMBER? -

ANY ADDITIONAL COMMENTS


-

SIGNATURE

SIGNATURES

A handwritten signature consisting of several overlapping, diagonal strokes, appearing as a stylized scribble.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, diagonal strokes, appearing as a stylized scribble.

ECo Australia Pty Ltd (Eco
Inspections)