

CUSTOMER **PM0010-Vehicle Servicing Records**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #10975		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	30/11/2018 - 08:00 AM	JOB COMPLETED	30/11/2018 - 04:25 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h05

DESCRIPTION

PM0010-Vehide Servicing Records
 1 BMN 153 Isuzi NPR 200

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE 15/11/2018
 VEHICLE REGISTRATION? Truck 6 1BMN153
 DESCRIPTION OF WORK DONE Mnor service oil and filter change including
 Front brake service replace front shoes and drums
 PI NUMBER P4114
 VALUE OF WORK DONE 1,108



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? No

SERVICE INFO

CURRENT ODOMETER READING KMS 482,888
 NEXT SERVICE DUE AT? 493,000
 WAS THE OIL & FILTER CHANGED? Yes
 WAS THE AIR FILTER CHANGED? Yes
 WERE THE BRAKE PADS CHANGED? Yes

COMMENTS SECTION


CPAR ISSUED? -

CPAR REFERENCE NUMBER? -


ANY ADDITIONAL COMMENTS -

SIGNATURE

SIGNATURES

A handwritten signature consisting of several overlapping, sweeping lines that form a complex, abstract shape.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, sweeping lines that form a complex, abstract shape, similar to the one on the left.

ECo Australia Pty Ltd (Eco
Inspections)