



CUSTOMER PM0010-Vehicle Servicing Records  
Monthly

JOB #6111		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	02/08/2018 - 08:00 AM	JOB COMPLETED	02/08/2018 - 12:04 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h37

DESCRIPTION

PM0010-Vehide Servicing Records 1EMF 419

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE 05/07/2018

VEHICLE REGISTRATION? Truck 5 Isuzu 1EMMF419

DESCRIPTION OF WORK DONE Investigate lack of power, Found to be Bearing on Turbo unit, Fitted new Garrett turbo unit, cleaned out oil and Debris from intake pipes and inter cooler

PI NUMBER 3797

VALUE OF WORK DONE -



Picture Of The Receipt

SERVICE INFO

CURRENT ODOMETER READING KMS 424,284

NEXT SERVICE DUE AT? 435,000

WAS THE OIL & FILTER CHANGED? No

WAS THE AIR FILTER CHANGED? No

WERE THE BRAKE PADS CHANGED? No


COMMENTS SECTION

CPAR ISSUED? -


CPAR REFERENCE NUMBER? -

ANY ADDITIONAL COMMENTS Investigate loss of power, Found to be main Turbo bearings failing, Fitted new Turbo, Garret Turbo GT2560LS, Replaced Engine oil and Coolant

SIGNATURE

A handwritten signature consisting of several overlapping, fluid strokes in black ink.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, fluid strokes in black ink, similar in style to the first signature.

ECo Australia Pty Ltd (Eco  
Inspections)