

**CUSTOMER** **PM0010-Vehicle Servicing Records**  
 Revision: Version 4 Effective Date: 13 July 2018  
 Issued By: Steve Claridge Approved By: Mark Keay

JOB #13411		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	25/01/2019 - 08:00 AM	JOB COMPLETED	25/01/2019 - 11:23 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h03

**DESCRIPTION**

Truck 5 Isuzu 1EMMF419

**PM0010-VEHICLE SERVICING RECORDS**

DATE OF JOB DONE 18/12/2018  
 VEHICLE REGISTRATION? Truck 5 Isuzu 1EMMF419  
 DESCRIPTION OF WORK DONE Puncture Repair  
 PI NUMBER 4201  
 VALUE OF WORK DONE -



Picture Of The Receipt

**SPARE PARTS**

WERE ANY SPARE PARTS PURCHASED? Yes  
 WHAT SPARES WERE PURCHASED? Replaced inner tube on truck due to Puncture  
 HOW MUCH DID THE SPARES COST? 40.00

**SERVICE INFO**


CURRENT ODOMETER READING KMS -  
 NEXT SERVICE DUE AT? -  
 WAS THE OIL & FILTER CHANGED? -  
 WAS THE AIR FILTER CHANGED? -  
 WERE THE BRAKE PADS CHANGED? -

**COMMENTS SECTION**

CPAR ISSUED? -  
CPAR REFERENCE NUMBER? -  
ANY ADDITIONAL COMMENTS -  
SIGNATURE

**SIGNATURES**

---

A handwritten signature in black ink, consisting of several overlapping loops and a vertical stroke extending downwards.

PM0010-Vehicle Servicing Records