

CUSTOMER **PM0010-Vehicle Servicing Records**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay

JOB #13412		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	25/01/2019 - 08:00 AM	JOB COMPLETED	25/01/2019 - 12:32 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h02

DESCRIPTION

Truck 4 Canter 1CEM814

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE 19/12/2018
 VEHICLE REGISTRATION? Truck 4 Canter 1CEM814
 DESCRIPTION OF WORK DONE Replacement of front tyre
 PI NUMBER 4202
 VALUE OF WORK DONE -



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? Yes
 WHAT SPARES WERE PURCHASED? Front tyre replacement Maxxis 700R16
 HOW MUCH DID THE SPARES COST? 225.00


SERVICE INFO

CURRENT ODOMETER READING KMS -
 NEXT SERVICE DUE AT? -
 WAS THE OIL & FILTER CHANGED? -
 WAS THE AIR FILTER CHANGED? -
 WERE THE BRAKE PADS CHANGED? -

COMMENTS SECTION

CPAR ISSUED? -
CPAR REFERENCE NUMBER? -
ANY ADDITIONAL COMMENTS -
SIGNATURE

SIGNATURES

A handwritten signature in black ink, consisting of several overlapping loops and strokes, positioned above the company name.

ECo Australia Pty Ltd (Eco
Inspections)