

CUSTOMER **PM0010-Vehicle Servicing Records**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay

JOB #15574		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	19/02/2019 - 08:00 AM	JOB COMPLETED	19/02/2019 - 12:46 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h04

DESCRIPTION

TRUCK 6 1BMN153

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE 01/02/2019
 VEHICLE REGISTRATION? Truck 6 1BMN153
 DESCRIPTION OF WORK DONE Replacement of two Front Tyres
 PI NUMBER P4267
 VALUE OF WORK DONE -



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? Yes
 WHAT SPARES WERE PURCHASED? 2 Maxxis Tyres 195/85R16
 HOW MUCH DID THE SPARES COST? 440.00


SERVICE INFO

CURRENT ODOMETER READING KMS -
 NEXT SERVICE DUE AT? -
 WAS THE OIL & FILTER CHANGED? -
 WAS THE AIR FILTER CHANGED? -
 WERE THE BRAKE PADS CHANGED? -

COMMENTS SECTION

CPAR ISSUED? -
CPAR REFERENCE NUMBER? -
ANY ADDITIONAL COMMENTS -
SIGNATURE

SIGNATURES

A handwritten signature consisting of several overlapping, fluid loops and lines, rendered in black ink.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, fluid loops and lines, rendered in black ink.

ECo Australia Pty Ltd (Eco
Inspections)