

CUSTOMER **PM0010-Vehicle Servicing Records**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #22680		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	05/07/2019 - 09:27 AM	JOB COMPLETED	20/02/2019 - 09:34 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h04

DESCRIPTION

Hyundai Getz

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE 20/02/2019
 VEHICLE REGISTRATION? Mitsubishi 380 1GAZ490
 DESCRIPTION OF WORK DONE Minor 4 cyl service replace both worn drive shafts
 PI NUMBER 4298
 VALUE OF WORK DONE 177.00



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? Yes
 WHAT SPARES WERE PURCHASED? Left and right front drive shafts
 HOW MUCH DID THE SPARES COST? 423.20


SERVICE INFO

CURRENT ODOMETER READING KMS 172,164
 NEXT SERVICE DUE AT? 182,000
 WAS THE OIL & FILTER CHANGED? Yes
 WAS THE AIR FILTER CHANGED? No
 WERE THE BRAKE PADS CHANGED? No


COMMENTS SECTION

CPAR ISSUED? -
CPAR REFERENCE NUMBER? -
ANY ADDITIONAL COMMENTS -
SIGNATURE

SIGNATURES

A handwritten signature consisting of several overlapping, fluid loops and strokes, rendered in black ink.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, fluid loops and strokes, rendered in black ink.

E'Co Australia Pty Ltd (Eco
Inspections)