

**CUSTOMER** **PM0010-Vehicle Servicing Records**  
 Revision: Version 4 Effective Date: 13 July 2018  
 Issued By: Steve Claridge Approved By: Mark Keay

JOB #16210		JOB REPORT	
JOB TYPE	<b>Internal Audits</b>	TECHNICIAN	<b>Eco Inspections</b>
SCHEDULED	<b>06/03/2019 - 08:00 AM</b>	JOB COMPLETED	<b>06/03/2019 - 11:19 AM</b>
SCHEDULED DURATION	<b>01h00</b>	COMPLETED DURATION	<b>00h04</b>

**DESCRIPTION**

TRUCK 5 IZUZI 1EMF 419

**PM0010-VEHICLE SERVICING RECORDS**

DATE OF JOB DONE 19/02/2019  
 VEHICLE REGISTRATION? Truck 5 Isuzu 1EMMF419  
 DESCRIPTION OF WORK DONE 2 Front Tyres replaced Maxxis 195/85R16  
 PI NUMBER 4293  
 VALUE OF WORK DONE -



Picture Of The Receipt

**SPARE PARTS**

WERE ANY SPARE PARTS PURCHASED? Yes  
 WHAT SPARES WERE PURCHASED? 2 Front Tyres Replaced Maxxis 195/85R16  
 HOW MUCH DID THE SPARES COST? 520.00

**SERVICE INFO**

CURRENT ODOMETER READING KMS -  
 NEXT SERVICE DUE AT? -  
 WAS THE OIL & FILTER CHANGED? -  
 WAS THE AIR FILTER CHANGED? -  
 WERE THE BRAKE PADS CHANGED? -

**COMMENTS SECTION**

CPAR ISSUED? -  
CPAR REFERENCE NUMBER? -  
ANY ADDITIONAL COMMENTS -  
SIGNATURE

**SIGNATURES**

---

A handwritten signature consisting of several overlapping, curved lines, appearing to be a stylized 'S' or similar character.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, curved lines, appearing to be a stylized 'S' or similar character.

ECo Australia Pty Ltd (Eco  
Inspections)