

CUSTOMER **PM0010-Vehicle Servicing Records**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay

JOB #22661		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	04/07/2019 - 02:16 PM	JOB COMPLETED	20/03/2019 - 02:26 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h09

DESCRIPTION

Truck 8 Isuzu Deli 1CLN006

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE 20/03/2019
 VEHICLE REGISTRATION? Truck 8 Isuzu Deli 1CLN006 Vin JAANFR66LV7102319 Engine 4HF1502526 Year 1997
 DESCRIPTION OF WORK DONE Investigate vehicle stuck in 3rd gear
 Found to be gear shift linkage broken
 PI NUMBER 4345
 VALUE OF WORK DONE 1,000.00



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? Yes
 WHAT SPARES WERE PURCHASED? Shift linkage, 4 Litres Manual transmission oil
 HOW MUCH DID THE SPARES COST? 91.00


SERVICE INFO

CURRENT ODOMETER READING KMS 526,977
 NEXT SERVICE DUE AT? 533,000 Kms
 WAS THE OIL & FILTER CHANGED? No
 WAS THE AIR FILTER CHANGED? No
 WERE THE BRAKE PADS CHANGED? No

COMMENTS SECTION

CPAR ISSUED? -
CPAR REFERENCE NUMBER? -
ANY ADDITIONAL COMMENTS -
SIGNATURE

SIGNATURES

A handwritten signature consisting of several overlapping, curved lines.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, curved lines, similar to the one on the left.

E'Co Australia Pty Ltd (Eco
Inspections)