

CUSTOMER

PM0010-Vehicle Servicing Records
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #22659		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	04/07/2019 - 12:06 PM	JOB COMPLETED	02/04/2019 - 12:36 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h08

DESCRIPTION

IZUZI TRUCK 5 1EMF 419

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE: 02/04/2019
 VEHICLE REGISTRATION?: Truck 5 Isuzu 1EMMF419 Vin JAANPR7SL67100602 Engine No 4HK1448032 Year 2006
 DESCRIPTION OF WORK DONE: Battery light on Alternator burnt out,Supply and install new Alternator.
 PI NUMBER: 4370
 VALUE OF WORK DONE: 770.00



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? No

SERVICE INFO

CURRENT ODOMETER READING KMS -
 NEXT SERVICE DUE AT? -
 WAS THE OIL & FILTER CHANGED? -
 WAS THE AIR FILTER CHANGED? -
 WERE THE BRAKE PADS CHANGED? -

COMMENTS SECTION


CPAR ISSUED? -
 CPAR REFERENCE NUMBER? -

ANY ADDITIONAL COMMENTS


-

SIGNATURE

SIGNATURES

A handwritten signature consisting of several overlapping, fluid loops and a vertical stroke extending downwards.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, fluid loops and a vertical stroke extending downwards.

ECo Australia Pty Ltd (Eco
Inspections)