

**CUSTOMER** **PM0010-Vehicle Servicing Records**  
 Revision: Version 4 Effective Date: 13 July 2018  
 Issued By: Steve Claridge Approved By: Mark Keay

JOB #22660		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	04/07/2019 - 02:00 PM	JOB COMPLETED	03/05/2019 - 02:04 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h03

**DESCRIPTION**

Truck 8 1CLN 006

**PM0010-VEHICLE SERVICING RECORDS**

DATE OF JOB DONE 03/05/2019  
 VEHICLE REGISTRATION? Truck 8 Isuzu Deli 1CLN006 Vin JAANFR66LV7102319 Engine 4HF1502526 Year 1997  
 DESCRIPTION OF WORK DONE Replaced new Inner Tube  
 PI NUMBER 4437  
 VALUE OF WORK DONE -



Picture Of The Receipt

**SPARE PARTS**

WERE ANY SPARE PARTS PURCHASED? Yes  
 WHAT SPARES WERE PURCHASED? Inner Tube  
 HOW MUCH DID THE SPARES COST? 35.00

**SERVICE INFO**

CURRENT ODOMETER READING KMS -  
 NEXT SERVICE DUE AT? -  
 WAS THE OIL & FILTER CHANGED? -  
 WAS THE AIR FILTER CHANGED? -  
 WERE THE BRAKE PADS CHANGED? -

**COMMENTS SECTION**


CPAR ISSUED? -  
CPAR REFERENCE NUMBER? -  
ANY ADDITIONAL COMMENTS -  
SIGNATURE

**SIGNATURES**

---

A handwritten signature in black ink, consisting of several overlapping loops and a trailing stroke.

PM0010-Vehicle Servicing Records

A handwritten signature in black ink, consisting of several overlapping loops and a trailing stroke, similar to the one on the left.

E'Co Australia Pty Ltd (Eco  
Inspections)