



CUSTOMER

PM0010-Vehicle Servicing Records
Revision: Version 4 Effective Date: 13 July 2018
Issued By: Steve Claridge Approved By: Mark Keay


Table with 4 columns: JOB #22656, JOB TYPE, SCHEDULED, SCHEDULED DURATION, Internal Audits, TECHNICAL, JOB COMPLETED, COMPLETED DURATION, Eco Inspections, 30/05/2019 - 09:45 AM, 00h03

DESCRIPTION

TRUCK 5 IZUZI 1EMF 419

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE 30/05/2019
VEHICLE REGISTRATION? Truck 5 Isuzu 1EMMF419 Vin JAANPR7SL67100602 Engine No 4HK1448032 Year 2006
DESCRIPTION OF WORK DONE 4 Cylinder Service oil change fluid check.
PI NUMBER 4482
VALUE OF WORK DONE 228.00



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? No

SERVICE INFO

CURRENT ODOMETER READING KMS 458,934
NEXT SERVICE DUE AT? 470,000
WAS THE OIL & FILTER CHANGED? Yes
WAS THE AIR FILTER CHANGED? No
WERE THE BRAKE PADS CHANGED? No

COMMENTS SECTION

CPAR ISSUED? -
CPAR REFERENCE NUMBER? -

ANY ADDITIONAL COMMENTS


-

SIGNATURE

SIGNATURES

A handwritten signature consisting of several overlapping, fluid strokes in black ink.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, fluid strokes in black ink, similar in style to the first signature.

ECo Australia Pty Ltd (Eco
Inspections)