

CUSTOMER **PM0010-Vehicle Servicing Records**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #22657		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	04/07/2019 - 09:56 AM	JOB COMPLETED	30/05/2019 - 10:10 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h09

DESCRIPTION

Mitsubishi Canter 1CEM 814

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE 30/05/2019
 VEHICLE REGISTRATION? Truck 4 Canter 1CEM814 Vin JLFFB3PEOKJ0002 Engine No 4D34R30285 Year 2006
 DESCRIPTION OF WORK DONE 4 Cyl Service oil filter change,
 Replace broken sway bar links
 PI NUMBER 4483
 VALUE OF WORK DONE 213.000



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? Yes
 WHAT SPARES WERE PURCHASED? Replaced front sway bar links
 HOW MUCH DID THE SPARES COST? 157.00

SERVICE INFO

CURRENT ODOMETER READING KMS 350,636
 NEXT SERVICE DUE AT? 361,000
 WAS THE OIL & FILTER CHANGED? Yes
 WAS THE AIR FILTER CHANGED? No
 WERE THE BRAKE PADS CHANGED? No

COMMENTS SECTION

CPAR ISSUED? -
CPAR REFERENCE NUMBER? -
ANY ADDITIONAL COMMENTS -
SIGNATURE

SIGNATURES



PM0010-Vehicle Servicing Records



E'Co Australia Pty Ltd (Eco
Inspections)