

CUSTOMER **PM0010-Vehicle Servicing Records**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #22658		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	04/07/2019 - 10:39 AM	JOB COMPLETED	07/06/2019 - 11:09 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h29

DESCRIPTION

Mitsubishi Triton Ute 1 1DIU 436

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE 07/06/2019
 VEHICLE REGISTRATION? Mitsubishi Triton1 1DIU436 Vin No MMAERKA4OAD016078
 DESCRIPTION OF WORK DONE Puncture repair
 PI NUMBER 4504
 VALUE OF WORK DONE 25.00



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? No

SERVICE INFO

CURRENT ODOMETER READING KMS -
 NEXT SERVICE DUE AT? -
 WAS THE OIL & FILTER CHANGED? -
 WAS THE AIR FILTER CHANGED? -
 WERE THE BRAKE PADS CHANGED? -

COMMENTS SECTION


CPAR ISSUED? -
 CPAR REFERENCE NUMBER? -

ANY ADDITIONAL COMMENTS

-

SIGNATURE

SIGNATURES

A handwritten signature consisting of several overlapping, fluid loops and a vertical stroke extending downwards from the center.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, fluid loops and a vertical stroke extending downwards from the center, identical to the signature on the left.

ECo Australia Pty Ltd (Eco
Inspections)