

**CUSTOMER** **PM0010-Vehicle Servicing Records**  
 Revision: Version 4 Effective Date: 13 July 2018  
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #24301		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	24/07/2019 - 09:17 AM	JOB COMPLETED	24/07/2019 - 09:41 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h20

**DESCRIPTION**

Peugeot 307

**PM0010-VEHICLE SERVICING RECORDS**

DATE OF JOB DONE 05/07/2019  
 VEHICLE REGISTRATION? Peugeot 3081BRX685 Vin No  
 DESCRIPTION OF WORK DONE Minor 4 cyl service,replace worn left rack end,w heel Alignment  
 PI NUMBER P4598  
 VALUE OF WORK DONE 305.00



Picture Of The Receipt

**SPARE PARTS**

WERE ANY SPARE PARTS PURCHASED? Yes  
 WHAT SPARES WERE PURCHASED? Left hand Rack end  
 HOW MUCH DID THE SPARES COST? 90.00

**SERVICE INFO**


CURRENT ODOMETER READING KMS 169,450  
 NEXT SERVICE DUE AT? 180,00  
 WAS THE OIL & FILTER CHANGED? Yes  
 WAS THE AIR FILTER CHANGED? No  
 WERE THE BRAKE PADS CHANGED? No

**COMMENTS SECTION**

CPAR ISSUED? -  
CPAR REFERENCE NUMBER? -  
ANY ADDITIONAL COMMENTS -  
SIGNATURE

**SIGNATURES**

---

A handwritten signature consisting of several overlapping, loopy strokes in black ink.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, loopy strokes in black ink, identical to the one on the left.

E'Co Australia Pty Ltd (Eco  
Inspections)