

**CUSTOMER** **PM0010-Vehicle Servicing Records**  
 Revision: Version 4 Effective Date: 13 July 2018  
 Issued By: Steve Claridge Approved By: Mark Keay

JOB #24302		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	24/07/2019 - 11:14 AM	JOB COMPLETED	24/07/2019 - 12:18 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h03

**DESCRIPTION**

isuzi NPR 200 1BMN 153

**PM0010-VEHICLE SERVICING RECORDS**

DATE OF JOB DONE 05/07/2019  
 VEHICLE REGISTRATION? Truck 6 Isuzi Truck 1BMN 153 Vin JAANPR70L37102230 Year 2003  
 DESCRIPTION OF WORK DONE Replace 2 Front Tyres as worn to limit  
 PI NUMBER 4579  
 VALUE OF WORK DONE -



Picture Of The Receipt

**SPARE PARTS**

WERE ANY SPARE PARTS PURCHASED? Yes  
 WHAT SPARES WERE PURCHASED? 2 Front Tyres replaced  
 HOW MUCH DID THE SPARES COST? 440.00

**SERVICE INFO**


CURRENT ODOMETER READING KMS -  
 NEXT SERVICE DUE AT? -  
 WAS THE OIL & FILTER CHANGED? -  
 WAS THE AIR FILTER CHANGED? -  
 WERE THE BRAKE PADS CHANGED? -

**COMMENTS SECTION**


CPAR ISSUED? -  
CPAR REFERENCE NUMBER? -  
ANY ADDITIONAL COMMENTS -  
SIGNATURE

**SIGNATURES**

---



PM0010-Vehicle Servicing Records



E'Co Australia Pty Ltd (Eco  
Inspections)