

**CUSTOMER** **PM0010-Vehicle Servicing Records**  
 Revision: Version 4 Effective Date: 13 July 2018  
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #24303		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	24/07/2019 - 11:17 AM	JOB COMPLETED	24/07/2019 - 12:13 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h04

**DESCRIPTION**

iSUZU NPR Flatbed Truck 8  
 1CLN 006

**PM0010-VEHICLE SERVICING RECORDS**

DATE OF JOB DONE 05/07/2019  
 VEHICLE REGISTRATION? Truck 8 Isuzu Deli 1CLN006 Vin JAANFR66LV7102319 Engine 4HF1502526 Year 1997  
 DESCRIPTION OF WORK DONE Mnor 4 Cyl Service grease and lube  
 Repair broken weld on exhaust and insert a sleeve for extra strength  
 PI NUMBER 4599  
 VALUE OF WORK DONE 423.00



Picture Of The Receipt

**SPARE PARTS**

WERE ANY SPARE PARTS PURCHASED? No

**SERVICE INFO**

CURRENT ODOMETER READING KMS 534,194  
 NEXT SERVICE DUE AT? 544,200  
 WAS THE OIL & FILTER CHANGED? Yes  
 WAS THE AIR FILTER CHANGED? No  
 WERE THE BRAKE PADS CHANGED? No

**COMMENTS SECTION**

CPAR ISSUED? -


CPAR REFERENCE NUMBER? -

ANY ADDITIONAL COMMENTS -


SIGNATURE

**SIGNATURES**

---

A handwritten signature consisting of several overlapping loops and a vertical stroke extending downwards.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping loops and a vertical stroke extending downwards.

ECo Australia Pty Ltd (Eco  
Inspections)