

**CUSTOMER** **PM0010-Vehicle Servicing Records**  
 Revision: Version 4 Effective Date: 13 July 2018  
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #24304		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	24/07/2019 - 02:22 PM	JOB COMPLETED	24/07/2019 - 02:42 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h17

**DESCRIPTION**

IZUSI NPR Truck 8 1CLN 006

**PM0010-VEHICLE SERVICING RECORDS**

DATE OF JOB DONE 24/07/2019  
 VEHICLE REGISTRATION? Truck 8 Isuzu Deli 1CLN006 V in JAANFR66LV7102319 Engine 4HF1502526 Year 1997  
 DESCRIPTION OF WORK DONE Balance 2 Front Tyres  
 PI NUMBER 4610  
 VALUE OF WORK DONE 50.00



Picture Of The Receipt

**SPARE PARTS**

WERE ANY SPARE PARTS PURCHASED? -

**SERVICE INFO**

CURRENT ODOMETER READING KMS -  
 NEXT SERVICE DUE AT? -  
 WAS THE OIL & FILTER CHANGED? -  
 WAS THE AIR FILTER CHANGED? -  
 WERE THE BRAKE PADS CHANGED? -

**COMMENTS SECTION**

CPAR ISSUED? -  
 CPAR REFERENCE NUMBER? -


ANY ADDITIONAL COMMENTS

-


SIGNATURE

**SIGNATURES**

---

A handwritten signature consisting of several overlapping, fluid loops and lines, rendered in black ink.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, fluid loops and lines, rendered in black ink.

ECo Australia Pty Ltd (Eco  
Inspections)