

**CUSTOMER** **PM0010-Vehicle Servicing Records**  
 Revision: Version 4 Effective Date: 13 July 2018  
 Issued By: Steve Claridge Approved By: Mark Keay

JOB #24364		JOB REPORT	
JOB TYPE	<b>Internal Audits</b>	TECHNICIAN	<b>Eco Inspections</b>
SCHEDULED	<b>26/07/2019 - 10:01 AM</b>	JOB COMPLETED	<b>26/07/2019 - 10:06 AM</b>
SCHEDULED DURATION	<b>01h00</b>	COMPLETED DURATION	<b>00h05</b>

**DESCRIPTION**

Hyundai Getz 1Esp 007

**PM0010-VEHICLE SERVICING RECORDS**

DATE OF JOB DONE 05/07/2019  
 VEHICLE REGISTRATION? Hyundai Getz 1BYR453  
 DESCRIPTION OF WORK DONE Mnor 4 Cyl service  
 PI NUMBER 4600  
 VALUE OF WORK DONE 179.00



Picture Of The Receipt

**SPARE PARTS**

WERE ANY SPARE PARTS PURCHASED? Yes  
 WHAT SPARES WERE PURCHASED? 2 x number plate globes  
 1 x break light globe  
 HOW MUCH DID THE SPARES COST? 19.00

**SERVICE INFO**

CURRENT ODOMETER READING KMS 192.770  
 NEXT SERVICE DUE AT? 203,000  
 WAS THE OIL & FILTER CHANGED? Yes  
 WAS THE AIR FILTER CHANGED? No  
 WERE THE BRAKE PADS CHANGED? No

**COMMENTS SECTION**


CPAR ISSUED? -  
CPAR REFERENCE NUMBER? -  
ANY ADDITIONAL COMMENTS -  
SIGNATURE

**SIGNATURES**

---

A handwritten signature consisting of several overlapping, fluid loops and lines, rendered in black ink.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, fluid loops and lines, rendered in black ink.

E'Co Australia Pty Ltd (Eco  
Inspections)