

CUSTOMER **PM0010-Vehicle Servicing Records**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #8589		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	12/07/2018 - 08:00 AM	JOB COMPLETED	25/09/2018 - 10:58 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h07

DESCRIPTION

Linde Fork Truck 2
 H2X392P02905

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE: 12/07/2018
 VEHICLE REGISTRATION?: Linde Fork Truck 1
 DESCRIPTION OF WORK DONE: Replaced Starter motor
 Replaced W/sealing ring
 Pulse generator
 PI NUMBER: 3859
 VALUE OF WORK DONE: -



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? Yes
 WHAT SPARES WERE PURCHASED? Starter motor
 Flange W/sealing ring
 HOW MUCH DID THE SPARES COST? 1,104.30

SERVICE INFO


CURRENT ODOMETER READING KMS: -
 NEXT SERVICE DUE AT?: -
 WAS THE OIL & FILTER CHANGED?: -
 WAS THE AIR FILTER CHANGED?: -
 WERE THE BRAKE PADS CHANGED?: -

COMMENTS SECTION

OPAR ISSUED?: -
 OPAR REFERENCE NUMBER?: -
 ANY ADDITIONAL COMMENTS: -
 SIGNATURE:

A handwritten signature consisting of several overlapping, fluid loops and lines, rendered in black ink.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, fluid loops and lines, rendered in black ink.

ECo Australia Pty Ltd (Eco
Inspections)