

**CUSTOMER** **PM0010-Vehicle Servicing Records**  
 Revision: Version 4 Effective Date: 13 July 2018  
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #24367		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	26/07/2019 - 12:27 PM	JOB COMPLETED	26/07/2019 - 12:31 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h02

**DESCRIPTION**

Peugot 307 1BRX 685

**PM0010-VEHICLE SERVICING RECORDS**

DATE OF JOB DONE 18/07/2019  
 VEHICLE REGISTRATION? Peugeot 3081BRX685 Vin No  
 DESCRIPTION OF WORK DONE Replace Front LH wheel bearings  
 PI NUMBER 4603  
 VALUE OF WORK DONE 317.50



Picture Of The Receipt

**SPARE PARTS**

WERE ANY SPARE PARTS PURCHASED? -

**SERVICE INFO**

CURRENT ODOMETER READING KMS -  
 NEXT SERVICE DUE AT? -  
 WAS THE OIL & FILTER CHANGED? -  
 WAS THE AIR FILTER CHANGED? -  
 WERE THE BRAKE PADS CHANGED? -

**COMMENTS SECTION**

CPAR ISSUED? -  
 CPAR REFERENCE NUMBER? -


ANY ADDITIONAL COMMENTS

-

SIGNATURE

**SIGNATURES**

---

A handwritten signature in black ink, consisting of several overlapping loops and a long horizontal stroke at the bottom.

PM0010-Vehicle Servicing Records

A handwritten signature in black ink, similar in style to the first signature, with overlapping loops and a long horizontal stroke.

ECo Australia Pty Ltd (Eco  
Inspections)