

CUSTOMER **PM0010-Vehicle Servicing Records**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #25412		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	12/08/2019 - 12:29 PM	JOB COMPLETED	12/08/2019 - 12:38 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h03

DESCRIPTION

Hyundai Getz 1ESP 007

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE 26/07/2019
 VEHICLE REGISTRATION? Hyundai Getz 1ESP 007
 DESCRIPTION OF WORK DONE Replaced collapsed offside engine mount & sun visor clip
 PI NUMBER 4630
 VALUE OF WORK DONE 220.00



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? No

SERVICE INFO

CURRENT ODOMETER READING KMS -
 NEXT SERVICE DUE AT? -
 WAS THE OIL & FILTER CHANGED? -
 WAS THE AIR FILTER CHANGED? -
 WERE THE BRAKE PADS CHANGED? -

COMMENTS SECTION

CPAR ISSUED? -
 CPAR REFERENCE NUMBER? -

ANY ADDITIONAL COMMENTS

-

SIGNATURE