

**CUSTOMER** **PM0010-Vehicle Servicing Records**  
 Revision: Version 4 Effective Date: 13 July 2018  
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #26231		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	30/08/2019 - 01:45 PM	JOB COMPLETED	30/08/2019 - 01:50 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h04

**DESCRIPTION**

Isuzu NPR 1BMN 153

**PM0010-VEHICLE SERVICING RECORDS**

DATE OF JOB DONE 21/08/2019  
 VEHICLE REGISTRATION? Truck 6 Isuzu Truck 1BMN 153 Vin JAANPR70L37102230 Year 2003  
 DESCRIPTION OF WORK DONE Replaced Clutch pressure plate, thrust bearing, machining of fly wheel, adjusted front & rear brakes.  
 PI NUMBER 4697  
 VALUE OF WORK DONE 1,549.00



Picture Of The Receipt

**SPARE PARTS**

WERE ANY SPARE PARTS PURCHASED? No

**SERVICE INFO**

CURRENT ODOMETER READING KMS -  
 NEXT SERVICE DUE AT? -  
 WAS THE OIL & FILTER CHANGED? -  
 WAS THE AIR FILTER CHANGED? -  
 WERE THE BRAKE PADS CHANGED? -

**COMMENTS SECTION**

CPAR ISSUED? -  
 CPAR REFERENCE NUMBER? -


ANY ADDITIONAL COMMENTS

-


SIGNATURE

**SIGNATURES**

---



PM0010-Vehicle Servicing Records



ECo Australia Pty Ltd (Eco  
Inspections)