

**CUSTOMER** **PM0010-Vehicle Servicing Records**  
 Revision: Version 4 Effective Date: 13 July 2018  
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #26423		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	02/09/2019 - 10:08 AM	JOB COMPLETED	02/09/2019 - 11:54 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h02

**DESCRIPTION**

Truck 6 1BMN 153

**PM0010-VEHICLE SERVICING RECORDS**

DATE OF JOB DONE 19/08/2019  
 VEHICLE REGISTRATION? Truck 6 Isuzi Truck 1BMN 153 Vin JAANPR70L37102230 Year 2003  
 DESCRIPTION OF WORK DONE Replaced front windscreen wiper blades  
 PI NUMBER 4680  
 VALUE OF WORK DONE -



Picture Of The Receipt

**SPARE PARTS**

WERE ANY SPARE PARTS PURCHASED? Yes  
 WHAT SPARES WERE PURCHASED? Windscreen wiper blades  
 HOW MUCH DID THE SPARES COST? 8.12

**SERVICE INFO**


CURRENT ODOMETER READING KMS -  
 NEXT SERVICE DUE AT? -  
 WAS THE OIL & FILTER CHANGED? -  
 WAS THE AIR FILTER CHANGED? -  
 WERE THE BRAKE PADS CHANGED? -

**COMMENTS SECTION**


CPAR ISSUED? -  
CPAR REFERENCE NUMBER? -  
ANY ADDITIONAL COMMENTS -  
SIGNATURE

**SIGNATURES**

---



PM0010-Vehicle Servicing Records



ECo Australia Pty Ltd (Eco  
Inspections)