

**CUSTOMER** **PM0010-Vehicle Servicing Records**  
 Revision: Version 4 Effective Date: 13 July 2018  
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #26424		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	02/09/2019 - 11:23 AM	JOB COMPLETED	02/09/2019 - 11:57 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h03

**DESCRIPTION**

Hyundai Getz 1ESP 007

**PM0010-VEHICLE SERVICING RECORDS**

DATE OF JOB DONE 20/08/2019  
 VEHICLE REGISTRATION? Hyundai Getz 1ESP 007  
 DESCRIPTION OF WORK DONE Windscreen wiper blades replaced  
 PI NUMBER 4681  
 VALUE OF WORK DONE -



Picture Of The Receipt

**SPARE PARTS**

WERE ANY SPARE PARTS PURCHASED? Yes  
 WHAT SPARES WERE PURCHASED? Windscreen wiper blades  
 HOW MUCH DID THE SPARES COST? 8.12

**SERVICE INFO**


CURRENT ODOMETER READING KMS -  
 NEXT SERVICE DUE AT? -  
 WAS THE OIL & FILTER CHANGED? -  
 WAS THE AIR FILTER CHANGED? -  
 WERE THE BRAKE PADS CHANGED? -

**COMMENTS SECTION**


CPAR ISSUED? -  
CPAR REFERENCE NUMBER? -  
ANY ADDITIONAL COMMENTS -  
SIGNATURE

**SIGNATURES**

---

A handwritten signature consisting of several overlapping, fluid loops and strokes, rendered in black ink.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, fluid loops and strokes, rendered in black ink.

ECo Australia Pty Ltd (Eco  
Inspections)