

**CUSTOMER** **PM0010-Vehicle Servicing Records**  
 Revision: Version 4 Effective Date: 13 July 2018  
 Issued By: Steve Claridge Approved By: Mark Keay

JOB #8590		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	25/09/2018 - 08:00 AM	JOB COMPLETED	25/09/2018 - 11:16 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h02

**DESCRIPTION**

Truck 4 1CEM 814

**PM0010-VEHICLE SERVICING RECORDS**

DATE OF JOB DONE 18/09/2018  
 VEHICLE REGISTRATION? Truck 4 Canter 1CEM814  
 DESCRIPTION OF WORK DONE Replacement of 3 Truck Tyres  
 PI NUMBER 3923  
 VALUE OF WORK DONE -



Picture Of The Receipt

**SPARE PARTS**

WERE ANY SPARE PARTS PURCHASED? Yes  
 WHAT SPARES WERE PURCHASED? 3 replacement Tyres  
 HOW MUCH DID THE SPARES COST? 675.00

**SERVICE INFO**


CURRENT ODOMETER READING KMS -  
 NEXT SERVICE DUE AT? -  
 WAS THE OIL & FILTER CHANGED? -  
 WAS THE AIR FILTER CHANGED? -  
 WERE THE BRAKE PADS CHANGED? -

**COMMENTS SECTION**

CPAR ISSUED? -  
CPAR REFERENCE NUMBER? -  
ANY ADDITIONAL COMMENTS -  
SIGNATURE

**SIGNATURES**

---

A handwritten signature consisting of several overlapping, sweeping loops, rendered in black ink.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, sweeping loops, rendered in black ink.

ECo Australia Pty Ltd (Eco  
Inspections)