

CUSTOMER **PM0010-Vehicle Servicing Records**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #8593		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	25/09/2018 - 08:00 AM	JOB COMPLETED	25/09/2018 - 12:33 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h04

DESCRIPTION

Truck 6 1BMN 153
 PM0010-Vehide Servicing Records

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE: 25/07/2018
 VEHICLE REGISTRATION?: Truck 6 1BMN153
 DESCRIPTION OF WORK DONE: Repairs to Tail lift, Burn out motor & Solenoid
 Replaced faulty control handset
 PI NUMBER: 3811
 VALUE OF WORK DONE: 1,265.60



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? No

SERVICE INFO

CURRENT ODOMETER READING KMS -
 NEXT SERVICE DUE AT? -
 WAS THE OIL & FILTER CHANGED? -
 WAS THE AIR FILTER CHANGED? -
 WERE THE BRAKE PADS CHANGED? -

COMMENTS SECTION


CPAR ISSUED? -

CPAR REFERENCE NUMBER? -


ANY ADDITIONAL COMMENTS -

SIGNATURE

SIGNATURES

A handwritten signature consisting of several overlapping, sweeping lines that form a stylized, abstract shape.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, sweeping lines that form a stylized, abstract shape, identical to the one on the left.

ECo Australia Pty Ltd (Eco
Inspections)