

CUSTOMER **PM0010-Vehicle Servicing Records**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #8596		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	25/09/2018 - 01:00 PM	JOB COMPLETED	25/09/2018 - 02:09 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h03

DESCRIPTION

Truck 5 1EMF 419

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE 29/06/2018
 VEHICLE REGISTRATION? Truck 5 Isuzu 1EMMF419
 DESCRIPTION OF WORK DONE Investigate lack of power, Found to be a fuel blockage,
 PI NUMBER 3767
 VALUE OF WORK DONE 243.76



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? No

SERVICE INFO

CURRENT ODOMETER READING KMS -
 NEXT SERVICE DUE AT? -
 WAS THE OIL & FILTER CHANGED? -
 WAS THE AIR FILTER CHANGED? -
 WERE THE BRAKE PADS CHANGED? -

COMMENTS SECTION


CPAR ISSUED? -
 CPAR REFERENCE NUMBER? -

ANY ADDITIONAL COMMENTS


-

SIGNATURE

SIGNATURES

A handwritten signature consisting of several overlapping, fluid strokes, appearing to be a stylized 'A' or similar character.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping, fluid strokes, appearing to be a stylized 'A' or similar character.

ECo Australia Pty Ltd (Eco
Inspections)