

CUSTOMER **PM0010-Vehicle Servicing Records**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay


JOB #8597		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	25/09/2018 - 01:00 PM	JOB COMPLETED	25/09/2018 - 02:56 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h02

DESCRIPTION

Truck 6 1BMN 153

PM0010-VEHICLE SERVICING RECORDS

DATE OF JOB DONE 27/06/2018
 VEHICLE REGISTRATION? Truck 6 1BMN153
 DESCRIPTION OF WORK DONE 10/15amp fuses
 PI NUMBER 3770
 VALUE OF WORK DONE -



Picture Of The Receipt

SPARE PARTS

WERE ANY SPARE PARTS PURCHASED? Yes
 WHAT SPARES WERE PURCHASED? 10/15amp fuses
 HOW MUCH DID THE SPARES COST? 25.58


SERVICE INFO

CURRENT ODOMETER READING KMS -
 NEXT SERVICE DUE AT? -
 WAS THE OIL & FILTER CHANGED? -
 WAS THE AIR FILTER CHANGED? -
 WERE THE BRAKE PADS CHANGED? -

COMMENTS SECTION

CPAR ISSUED? -
CPAR REFERENCE NUMBER? -
ANY ADDITIONAL COMMENTS -
SIGNATURE

SIGNATURES

A handwritten signature consisting of several overlapping loops and a long horizontal stroke extending to the right.

PM0010-Vehicle Servicing Records

A handwritten signature consisting of several overlapping loops and a long horizontal stroke extending to the right, similar to the one on the left.

ECo Australia Pty Ltd (Eco
Inspections)