

**CUSTOMER** **PM0002-Forklift Maintenance Inspection**  
**H2X392P02905**  
 Revision: Version 4 Effective Date: 13 July 2018  
 Issued By: Steve Claridge Approved By: Mark Keay


| JOB #6349          |                       | JOB REPORT         |                       |
|--------------------|-----------------------|--------------------|-----------------------|
| JOB TYPE           | Internal Audits       | TECHNICIAN         | Eco Inspections       |
| SCHEDULED          | 08/08/2018 - 10:11 AM | JOB COMPLETED      | 08/08/2018 - 10:19 AM |
| SCHEDULED DURATION | 01h00                 | COMPLETED DURATION | 00h07                 |

**DESCRIPTION**

PM0002-Forklift Maintenance Inspection H2X392P02905

**PM0010-VEHICLE SERVICING RECORDS**

DATE OF JOB DONE 12/07/2018  
 VEHICLE REGISTRATION? Linde Fork Truck 1  
 DESCRIPTION OF WORK DONE Engine repair 8mm ring gear/disk fabric kit  
 PI NUMBER 3860  
 VALUE OF WORK DONE 2,274.64



Picture Of The Receipt

**SPARE PARTS**

WERE ANY SPARE PARTS PURCHASED? Yes  
 WHAT SPARES WERE PURCHASED? Starter motor/Flange sealing ring/Pulse generator  
 HOW MUCH DID THE SPARES COST? -

**SERVICE INFO**


CURRENT ODOMETER READING KMS 0  
 NEXT SERVICE DUE AT? 0  
 WAS THE OIL & FILTER CHANGED? No  
 WAS THE AIR FILTER CHANGED? No  
 WERE THE BRAKE PADS CHANGED? No

**COMMENTS SECTION**


CPAR ISSUED? -  
CPAR REFERENCE NUMBER? -  
ANY ADDITIONAL COMMENTS -  
SIGNATURE

**SIGNATURES**

---



PM0002-Forklift Maintenance  
Inspection H2X392P02905



ECo Australia Pty Ltd (Eco  
Inspections)

**PICTURES**

---

