



**CUSTOMER**

**PM0003-Metal Detector Inspection**  
Revision: Version 4 Effective Date: 13 July 2018  
Issued By: Steve Claridge Approved By: Mark Keay

JOB #22116		JOB REPORT	
JOB TYPE	<b>Internal Audits</b>	TECHNICIAN	<b>Eco Inspections</b>
SCHEDULED	<b>24/07/2019 - 10:00 AM</b>	JOB COMPLETED	<b>24/07/2019 - 07:40 PM</b>
SCHEDULED DURATION	<b>01h00</b>	COMPLETED DURATION	<b>00h01</b>

**DESCRIPTION**

Metal Detector

**PM0003-METAL DETECTOR INSPECTION**

VISUAL INSPECTION	All working correctly	RUN ENVIRONMENT TEST?	All In Good Order
BLOW OUT ALL DEBRIS?	Yes	RUN CONVEYOR TEST?	All In Good Order
GENTLY WIPE BELT WITH MENTHOLATED SPRAY AND REMOVE ALL METAL OBJECTS?	Yes	CHECK AND TEST FUNCTIONALITY?	All In Good Order

**COSTS OF MAINTENANCE**

WAS ANY MONEY SPENT ON SERVICING? No

**COMMENTS SECTION**

ANY ADDITIONAL COMMENTS OR ISSUES -

SIGNATURE

**SIGNATURES**

PM0003-Metal Detector Inspection

E'Co Australia Pty Ltd (Eco Inspections)