



**CUSTOMER**

**PM0003-Metal Detector Inspection**  
Revision: Version 4 Effective Date: 13 July 2018  
Issued By: Steve Claridge Approved By: Mark Keay

| JOB #24296         |                              | JOB REPORT         |                              |
|--------------------|------------------------------|--------------------|------------------------------|
| JOB TYPE           | <b>Internal Audits</b>       | TECHNICIAN         | <b>Eco Inspections</b>       |
| SCHEDULED          | <b>30/08/2019 - 11:00 AM</b> | JOB COMPLETED      | <b>30/08/2019 - 11:16 AM</b> |
| SCHEDULED DURATION | <b>01h00</b>                 | COMPLETED DURATION | -                            |

**DESCRIPTION**

Metal Detector

**PM0003-METAL DETECTOR INSPECTION**

|   |                       |                               |                   |
|---|-----------------------|-------------------------------|-------------------|
| VISUAL INSPECTION   | All working correctly | RUN ENVIRONMENT TEST?         | All In Good Order |
| BLOW OUT ALL DEBRIS?  | Yes                   | RUN CONVEYOR TEST?            | All In Good Order |
| GENTLY WIPE BELT WITH MENTHOLATED SPRAY AND REMOVE ALL METAL OBJECTS? | Yes                   | CHECK AND TEST FUNCTIONALITY? | All In Good Order |

**COSTS OF MAINTENANCE**

WAS ANY MONEY SPENT ON SERVICING? No

**COMMENTS SECTION**

ANY ADDITIONAL COMMENTS OR ISSUES -

SIGNATURE

**SIGNATURES**

PM0003-Metal Detector Inspection

E'Co Australia Pty Ltd (Eco Inspections)