



CUSTOMER **PM0003-Metal Detector Inspection**  
Revision: Version 4 Effective Date: 13 July 2018  
Issued By: Steve Claridge Approved By: Mark Keay

JOB #8617		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	30/10/2018 - 10:00 AM	JOB COMPLETED	30/10/2018 - 01:27 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h03

**DESCRIPTION**

Metal Detector

**PM0003-METAL DETECTOR INSPECTION**

VISUAL INSPECTION	Very dusty <i>Vacuumed inside out side of machine Cleaned spindle wheels</i>	RUN ENVIRONMENT TEST?	All In Good Order
BLOW OUT ALL DEBRIS?	Yes <i>Badly build up with dust inside machine</i>	RUN CONVEYOR TEST?	Needs Attention <i>Tightened belt due to belt kept stopping with minimum weight</i>
GENTLY WIPE BELT WITH MENTHOLATED SPRAY AND REMOVE ALL METAL OBJECTS?	Yes	CHECK AND TEST FUNCTIONALITY?	All In Good Order

**COSTS OF MAINTENANCE**

WAS ANY MONEY SPENT ON SERVICING? -

**COMMENTS SECTION**

ANY ADDITIONAL COMMENTS OR ISSUES -

SIGNATURE

**SIGNATURES**

PM0003-Metal Detector Inspection

E'Co Australia Pty Ltd (Eco Inspections)