



**CUSTOMER**

**PM0003-Metal Detector Inspection**  
Revision: Version 4 Effective Date: 13 July 2018  
Issued By: Steve Claridge Approved By: Mark Keay

JOB #9603		JOB REPORT	
JOB TYPE	<b>Internal Audits</b>	TECHNICIAN	<b>Eco Inspections</b>
SCHEDULED	<b>30/11/2018 - 08:00 AM</b>	JOB COMPLETED	<b>30/11/2018 - 06:12 PM</b>
SCHEDULED DURATION	<b>01h00</b>	COMPLETED DURATION	<b>00h07</b>

**DESCRIPTION**

Metal Detector

**PM0003-METAL DETECTOR INSPECTION**

VISUAL INSPECTION	All in working condition	RUN ENVIRONMENT TEST?	All In Good Order
BLOW OUT ALL DEBRIS?	Yes <i>Done on a daily basis</i>	RUN CONVEYOR TEST?	All In Good Order
GENTLY WIPE BELT WITH MENTHOLATED SPRAY AND REMOVE ALL METAL OBJECTS?	Yes	CHECK AND TEST FUNCTIONALITY?	All In Good Order

**COSTS OF MAINTENANCE**

WAS ANY MONEY SPENT ON SERVICING? -

**COMMENTS SECTION**

ANY ADDITIONAL COMMENTS OR ISSUES -

SIGNATURE

**SIGNATURES**

PM0003-Metal Detector Inspection

E'Co Australia Pty Ltd (Eco Inspections)