

CUSTOMER **PM0003-Metal Detector Inspection**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay

JOB #15575		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	19/02/2019 - 08:00 AM	JOB COMPLETED	19/02/2019 - 12:40 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h06

DESCRIPTION

PM0003 Metal Detector Machine

PARTS

DATE ITEMS WERE BOUGHT?	29/01/2019	WHAT WAS BOUGHT?	Needle Detector Conveyor Belt
WHAT EQUIPMENT WAS THIS PURCHASED FOR?	Metal Detector	WHAT IS THE PI NUMBER?	4257
HOW MUCH WAS SPENT?	461.55	ADDITIONAL COMMENTS	-




Photo Of Receipt?

SIGNATURES

PM0003-Metal Detector Inspection

E'Co Australia Pty Ltd (Eco Inspections)