

CUSTOMER

PM0003-Metal Detector Inspection
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay

JOB #10685		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	02/07/2019 - 11:00 AM	JOB COMPLETED	18/04/2019 - 09:03 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h02

DESCRIPTION

Metal Detector

PM0003-METAL DETECTOR INSPECTION

VISUAL INSPECTION	All working correctly	RUN ENVIRONMENT TEST?	All In Good Order
BLOW OUT ALL DEBRIS?	Yes <input type="text" value="Done Daily"/>	RUN CONVEYOR TEST?	All In Good Order
GENTLY WIPE BELT WITH MENTHOLATED SPRAY AND REMOVE ALL METAL OBJECTS?	Yes <input type="text" value="Done Daily"/>	CHECK AND TEST FUNCTIONALITY?	All In Good Order

COSTS OF MAINTENANCE


WAS ANY MONEY SPENT ON SERVICING? No

COMMENTS SECTION


ANY ADDITIONAL COMMENTS OR ISSUES -

SIGNATURE

SIGNATURES



PM0003-Metal Detector Inspection



E'Co Australia Pty Ltd (Eco Inspections)