

CUSTOMER **PM0004-Blocking Machine Inspection**
 Revision: Version 4 Effective Date: 13 July 2018
 Issued By: Steve Claridge Approved By: Mark Keay

JOB #13386		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	22/02/2019 - 08:00 AM	JOB COMPLETED	22/02/2019 - 02:08 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h01

DESCRIPTION

Blocking Machine

PM0004-BLOCKING MACHINE INSPECTION

VISUAL INSPECTION	All working correctly
BLOW OUT ALL DEBRIS?	Yes
LUBRICATE WHERE NEEDED?	Yes
CHECK AND GREASE DOOR?	Yes
CHECK AND TEST FUNCTIONALITY?	All In Good Order

COSTS OF MAINTENANCE

WAS ANY MONEY SPENT ON SERVICING?	Yes
DESCRIPTION OF WORK DONE	replaced needle detector belt
HOW MUCH WAS SPENT?	461.45




Photo Of The Invoice

COMMENTS SECTION

ANY ADDITIONAL COMMENTS OR ISSUES -

SIGNATURE

SIGNATURES

PM0004-Blocking Machine Inspection

E'Co Australia Pty Ltd (Eco Inspections)