



CUSTOMER PM0006-Bailing Machine Inspection
Monthly

JOB #5129		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	23/07/2018 - 08:00 AM	JOB COMPLETED	24/07/2018 - 07:37 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h06

DESCRIPTION

Bailing Machine

PM0006-BAILING MACHINE INSPECTION

VISUAL INSPECTION	-	INSPECT THE AIR FILTER?	All In Good Order
ARE THERE ANY OIL LEAKS?	No	CHECK THAT MOUNTING BOLTS ARE TIGHT?	All In Good Order
CHECK HYDRAULIC OIL LEVEL?	Needs Attention <i>Topped up hydraulic oil</i>	INSPECT AND GREASE THE DOOR HINGES/HAND WHEEL?	All In Good Order

COSTS OF MAINTENANCE

WAS ANY MONEY SPENT ON SERVICING? No

COMMENTS SECTION

ANY ADDITIONAL COMMENTS OR ISSUES -

SIGNATURE

SIGNATURES

PM0006-Bailing Machine Inspection

E'Co Australia Pty Ltd (Eco Inspections)