



CUSTOMER **PM0006-Bailing Machine Inspection**  
Monthly

JOB #17339		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	02/07/2019 - 08:00 AM	JOB COMPLETED	22/05/2019 - 09:54 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h02

**DESCRIPTION**

Bailing Machine

**PM0006-BAILING MACHINE INSPECTION**

VISUAL INSPECTION	All working correctly	INSPECT THE AIR FILTER?	All In Good Order
ARE THERE ANY OIL LEAKS?	No	CHECK THAT MOUNTING BOLTS ARE TIGHT?	All In Good Order
CHECK HYDRAULIC OIL LEVEL?	All In Good Order	INSPECT AND GREASE THE DOOR HINGES/HAND WHEEL?	All In Good Order

**COSTS OF MAINTENANCE**

WAS ANY MONEY SPENT ON SERVICING? No

**COMMENTS SECTION**

ANY ADDITIONAL COMMENTS OR ISSUES -

SIGNATURE

**SIGNATURES**

PM0006-Bailing Machine Inspection

E'Co Australia Pty Ltd (Eco Inspections)