



CUSTOMER PM0006-Bailing Machine Inspection
Monthly

JOB #20209		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	02/07/2019 - 08:00 AM	JOB COMPLETED	20/06/2019 - 09:58 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h03

DESCRIPTION

Bailing Machine

PM0006-BAILING MACHINE INSPECTION

VISUAL INSPECTION	All working correctly	INSPECT THE AIR FILTER?	All In Good Order
ARE THERE ANY OIL LEAKS?	Yes <i>Hose leak on hydraulic hose on main lift requires attention</i>	CHECK THAT MOUNTING BOLTS ARE TIGHT?	All In Good Order
CHECK HYDRAULIC OIL LEVEL?	All In Good Order	INSPECT AND GREASE THE DOOR HINGES/HAND WHEEL?	-

COSTS OF MAINTENANCE

WAS ANY MONEY SPENT ON SERVICING? -

COMMENTS SECTION

ANY ADDITIONAL COMMENTS OR ISSUES Suspected oil leak inside machine investigated no leaks found machine cleaned thoroughly

SIGNATURE

SIGNATURES

PM0006-Bailing Machine Inspection