



CUSTOMER PM0006-Bailing Machine Inspection
Monthly

JOB #24300		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	30/08/2019 - 08:00 AM	JOB COMPLETED	30/08/2019 - 11:32 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h04

DESCRIPTION

Bailing Machine

PM0006-BAILING MACHINE INSPECTION

VISUAL INSPECTION	All working correctly	INSPECT THE AIR FILTER?	All In Good Order
	<i>Have noticed that foot is coming down quite fast on appearance when not under pressure,have investigated and looks like could be a fault on load bearing valve,Am now waiting for a quote for repair.</i>	CHECK THAT MOUNTING BOLTS ARE TIGHT?	Needs Attention <i>Have tightened foot bolts that appeared to be loose</i>
ARE THERE ANY OIL LEAKS?	No	INSPECT AND GREASE THE DOOR HINGES/HAND WHEEL?	All In Good Order
CHECK HYDRAULIC OIL LEVEL?	All In Good Order		

COSTS OF MAINTENANCE

WAS ANY MONEY SPENT ON SERVICING? -

COMMENTS SECTION

ANY ADDITIONAL COMMENTS OR ISSUES Have noticed that foot is coming down quite fast on appearance when not under pressure,have investigated and looks like could be a fault on load bearing valve,Am now waiting for a quote for repair.

SIGNATURE

SIGNATURES

PM0006-Bailing Machine Inspection

E'Co Australia Pty Ltd (Eco Inspections)