



CUSTOMER **PM0006-Bailing Machine Inspection**
Monthly

JOB #7156		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	20/09/2018 - 08:00 AM	JOB COMPLETED	21/09/2018 - 11:23 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h01

DESCRIPTION

Bailing Machine

PM0006-BAILING MACHINE INSPECTION

VISUAL INSPECTION	All in good working order	INSPECT THE AIR FILTER?	All In Good Order
ARE THERE ANY OIL LEAKS?	No	CHECK THAT MOUNTING BOLTS ARE TIGHT?	All In Good Order
CHECK HYDRAULIC OIL LEVEL?	All In Good Order	INSPECT AND GREASE THE DOOR HINGES/HAND WHEEL?	All In Good Order

COSTS OF MAINTENANCE

WAS ANY MONEY SPENT ON SERVICING? No

COMMENTS SECTION

ANY ADDITIONAL COMMENTS OR ISSUES -

SIGNATURE

SIGNATURES

PM0006-Bailing Machine Inspection

E'Co Australia Pty Ltd (Eco Inspections)