



CUSTOMER **PM0006-Bailing Machine Inspection**  
Monthly

JOB #8622		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	30/10/2018 - 08:00 AM	JOB COMPLETED	30/10/2018 - 01:31 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h01

**DESCRIPTION**

Bailing Machine

**PM0006-BAILING MACHINE INSPECTION**

VISUAL INSPECTION	All in good working order	INSPECT THE AIR FILTER?	All In Good Order
ARE THERE ANY OIL LEAKS?	No	CHECK THAT MOUNTING BOLTS ARE TIGHT?	All In Good Order
CHECK HYDRAULIC OIL LEVEL?	All In Good Order	INSPECT AND GREASE THE DOOR HINGES/HAND WHEEL?	All In Good Order <i>Re greased</i>

**COSTS OF MAINTENANCE**

WAS ANY MONEY SPENT ON SERVICING? -

**COMMENTS SECTION**

ANY ADDITIONAL COMMENTS OR ISSUES -

SIGNATURE

**SIGNATURES**

PM0006-Bailing Machine Inspection

E'Co Australia Pty Ltd (Eco Inspections)