



CUSTOMER **PM0006-Baling Machine Inspection**
Monthly

JOB #10690		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	06/03/2019 - 08:00 AM	JOB COMPLETED	20/12/2018 - 09:20 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h03

DESCRIPTION

Baling Machine

PM0006-BALING MACHINE INSPECTION

VISUAL INSPECTION	All in good order	INSPECT THE AIR FILTER?	All In Good Order
ARE THERE ANY OIL LEAKS?	No	CHECK THAT MOUNTING BOLTS ARE TIGHT?	All In Good Order
CHECK HYDRAULIC OIL LEVEL?	All In Good Order	INSPECT AND GREASE THE DOOR HINGES/HAND WHEEL?	All In Good Order

COSTS OF MAINTENANCE

WAS ANY MONEY SPENT ON SERVICING? No

COMMENTS SECTION

ANY ADDITIONAL COMMENTS OR ISSUES -

SIGNATURE

SIGNATURES

PM0006-Baling Machine Inspection

ECo Australia Pty Ltd (Eco Inspections)