



CUSTOMER **PM0006-Bailing Machine Inspection**
Monthly

JOB #13394		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	06/03/2019 - 08:00 AM	JOB COMPLETED	20/02/2019 - 09:12 AM
SCHEDULED DURATION	01h00	COMPLETED DURATION	00h03

DESCRIPTION

Bailing Machine

PM0006-BAILING MACHINE INSPECTION

VISUAL INSPECTION	All in good order	INSPECT THE AIR FILTER?	All In Good Order
ARE THERE ANY OIL LEAKS?	No <i>Topped up with hydro oil</i>	CHECK THAT MOUNTING BOLTS ARE TIGHT?	All In Good Order
CHECK HYDRAULIC OIL LEVEL?	All In Good Order	INSPECT AND GREASE THE DOOR HINGES/HAND WHEEL?	All In Good Order

COSTS OF MAINTENANCE

WAS ANY MONEY SPENT ON SERVICING? No

COMMENTS SECTION

ANY ADDITIONAL COMMENTS OR ISSUES -

SIGNATURE

SIGNATURES

PM0006-Bailing Machine Inspection

E'Co Australia Pty Ltd (Eco Inspections)