



CUSTOMER **PM0006-Bailing Machine Inspection**
Monthly

JOB #15608		JOB REPORT	
JOB TYPE	Internal Audits	TECHNICIAN	Eco Inspections
SCHEDULED	25/03/2019 - 08:00 AM	JOB COMPLETED	25/03/2019 - 12:06 PM
SCHEDULED DURATION	01h00	COMPLETED DURATION	-

DESCRIPTION

Bailing Machine

PM0006-BAILING MACHINE INSPECTION

VISUAL INSPECTION	All working correctly	INSPECT THE AIR FILTER?	All In Good Order
ARE THERE ANY OIL LEAKS?	No	CHECK THAT MOUNTING BOLTS ARE TIGHT?	All In Good Order
CHECK HYDRAULIC OIL LEVEL?	All In Good Order <i>Topped up tank</i>	INSPECT AND GREASE THE DOOR HINGES/HAND WHEEL?	All In Good Order

COSTS OF MAINTENANCE

WAS ANY MONEY SPENT ON SERVICING? No

COMMENTS SECTION

ANY ADDITIONAL COMMENTS OR ISSUES -

SIGNATURE

SIGNATURES

PM0006-Bailing Machine Inspection

E'Co Australia Pty Ltd (Eco Inspections)